

代碼	CDGM	代碼	HOYA	代碼	OHARA	代碼	SCHOTT
497816	H-FK61	497-816	FCD1	497816	S-FPL51	497816	N-PK52A
457903	H-FK71	457-903	FCD10				
618634	H-ZPK1	618-634	PCD4	618-634	S-PHM52		
603655	H-ZPK2			603655			
470668	H-QK1	471-673	FC1	471674	FSL1	471673	FK1
487700	H-QK3						
487704	H-QK3L	487-704	FC5	487702	S-FSL5	487704	N-FK5
500660	H-K2	510-634	BSC4	500660	BSL4	500658	BK4
505647	H-K3						
508611	K4A	508-613	ZNC7	508608	ZSL7	508612	ZKN7
510634	H-K5	510-634	BSC1	510636	BSL1	510635	BK1
511605	H-K6	511605	C7	511605	NSL7	511604	K7
515606	H-K7						
517642	H-K9L	517-642	BSC7	517641	S-BSL7	517642	N-BK7
518590	H-K10	518-590	E-C3	518590	S-NSL3		
526602	H-K11	526-601	BACL1	526600	NSL21		
522592	H-K50	522595	C5	522598	S-NSL5	522595	N-K5
523586	H-K51	523586	C12	523585	NSL51		
530605	H-BaK1						
540597	H-BaK2	540-597	BAC2	540595	S-BAL12	540597	N-BAK2
547628	H-BaK3			548628	BAL21		
552634	H-BaK4	552-634	PCD3	552638	BAL23	552635	N-PSK3
561583	H-BaK5						
564608	H-BaK6	564-608	BACD11	564607	S-BAL41	564608	N-SK11
569560	H-BaK7	569-560	BAC4	569563	S-BAL14	569560	N-BAK4
573575	H-BaK8	573-575	BAC1	573576	S-BAL11	573576	N-BAK1

569629	<b>H-ZK1</b>	569-631	<b>PCD2</b>	569631	<b>PSK2</b>	569631	<b>S-BAL22</b>
583595	<b>H-ZK2</b>	583-595	<b>BACD12</b>	583594	<b>S-BAL42</b>	583595	<b>SK12</b>
589613	<b>H-ZK3</b>	5896-13	<b>BACD5</b>	589612	<b>S-BAL35</b>	589613	<b>N-SK5</b>
609589	<b>H-ZK4</b>	613-586	<b>BACD3</b>	609590	<b>BSM3</b>	609589	<b>SK3</b>
611558	<b>H-ZK5</b>						
613586	<b>H-ZK6</b>	613-586	<b>BACD4</b>	613587	<b>S-BSM4</b>	613586	<b>N-SK4</b>
613606	<b>H-ZK7</b>						
614551	<b>H-ZK8</b>	614-551	<b>BACD9</b>	614550	<b>S-BSM9</b>		
620603	<b>H-ZK9B</b>	620-603	<b>BACD16</b>	620603	<b>S-BSM16</b>	620603	<b>N-SK16</b>
622567	<b>H-ZK10</b>						
623569	<b>H-ZK10L</b>	623-569	<b>E-BACD10</b>	623570	<b>S-BSM10</b>	622570	<b>N-SK10</b>
639555	<b>H-ZK11</b>	639-555	<b>BACD18</b>	639554	<b>S-BSM18</b>	639554	<b>N-SK18</b>
603606	<b>H-ZK14</b>	603-607	<b>BACD14</b>	603607	<b>S-BSM14</b>	603606	<b>N-SK14</b>
617539	<b>H-ZK20</b>						
623581	<b>H-ZK21</b>	623-581	<b>BACD15</b>	623582	<b>S-BSM15</b>	623580	<b>N-SK15</b>
607567	<b>H-ZK50</b>	607-567	<b>BACD2</b>	607568	<b>S-BSM2</b>	607567	<b>N-SK2</b>
660574	<b>H-LaK1</b>	660-573	<b>LAC11</b>	658573	<b>S-LAL11</b>	660573	<b>LAK11</b>
692545	<b>H-LaK2</b>						
747510	<b>H-LaK3</b>						
640602	<b>H-LaK4L</b>	640-602	<b>LACL60</b>	640601	<b>S-BSM81</b>	640601	<b>N-LAK21</b>
678555	<b>H-LaK5A</b>	678-555	<b>LAC12</b>	678553	<b>S-LAL12</b>	678552	<b>N-LAK12</b>
694534	<b>H-LaK6A</b>	694-533	<b>LAC13</b>	694532	<b>S-LAL13</b>	694533	<b>N-LAK13</b>
713538	<b>H-LaK7A</b>	713-539	<b>LAC8</b>	713539	<b>S-LAL8</b>	713538	<b>N-LAK8</b>
720503	<b>H-LaK8A</b>	720-503	<b>LAC10</b>	720502	<b>S-LAL10</b>	720506	<b>N-LAK10</b>
651559	<b>H-LaK10</b>			651562	<b>S-LAL54</b>	651559	<b>N-LAK22</b>
665546	<b>H-LaK11</b>						
697562	<b>H-LaK12</b>			697565	<b>LAL64</b>	697562	<b>LAK24</b>

652584	<b>H-LaK50A</b>	652-584	<b>LAC7</b>	652585	<b>S-LAL7</b>	652585	<b>N-LAK7</b>
697555	<b>H-LaK51A</b>	697-555	<b>LAC14</b>	697555	<b>S-LAL14</b>	697554	<b>N-LAK14</b>
729547	<b>H-LaK52</b>	729-547	<b>TAC8</b>	729547	<b>S-LAL18</b>	729545	<b>N-LAK34</b>
755523	<b>H-LaK53A</b>	755-523	<b>TAC6</b>	755523	<b>S-YGH51</b>	754523	<b>N-LAK33A</b>
734515	<b>H-LaK54</b>	734-511	<b>TAC4</b>	734515	<b>S-LAL59</b>		
691548	<b>H-LaK59</b>	691-547	<b>LAC9</b>	691548	<b>S-LAL9</b>	691547	<b>N-LAK9</b>
741527	<b>H-LaK61</b>	741-526	<b>TAC2</b>	741527	<b>S-LAL61</b>		
670517	<b>H-LaK67</b>			670516	<b>LAL53</b>		
517522	<b>H-KF6</b>	517-522	<b>E-CF6</b>	517524	<b>S-NSL36</b>		
548459	<b>QF1</b>	548-458	<b>FEL1</b>	548458	<b>PBL1</b>	548458	<b>LLF1</b>
548458	<b>H-QF1</b>	548-458	<b>E-FEL1</b>	548458	<b>S-TIL1</b>	548458	<b>N-LLF1</b>
575413	<b>QF3</b>	575-415	<b>FL7</b>	575415	<b>PBL27</b>	575415	<b>LF7</b>
575415	<b>H-QF3</b>			575415	<b>S-TIL27</b>		
582420	<b>QF5</b>						
532488	<b>QF6</b>	532-488	<b>FEL6</b>	532489	<b>PBL6</b>		
532488	<b>H-QF6A</b>	532-488	<b>E-FEL6</b>	532489	<b>S-TIL6</b>	532489	<b>N-LLF6</b>
541472	<b>QF8</b>	541-472	<b>FEL2</b>	541472	<b>PBL2</b>		
541472	<b>H-QF8</b>	541-472	<b>E-FEL2</b>	541472	<b>S-TIL2</b>		
596392	<b>H-QF14</b>	596-392	<b>E-F8</b>				
581409	<b>QF50</b>	581-409	<b>FL5</b>	581407	<b>PBL25</b>	581409	<b>LF5</b>
581409	<b>H-QF50</b>	581-409	<b>E-FL5</b>	581407	<b>S-TIL25</b>	581409	<b>N-LF5</b>
567428	<b>H-QF56</b>	567-428	<b>E-FL6</b>	567428	<b>S-TIL26</b>		
603380	<b>H-F1</b>	603-380	<b>E-F5</b>	603380	<b>S-TIM5</b>		
603380	<b>F1</b>	603-380	<b>F5</b>	603380	<b>PBM5</b>	603380	<b>F5</b>
613370	<b>F2</b>	613-370	<b>F3</b>	613370	<b>PBM3</b>	613370	<b>F3</b>
613370	<b>H-F2</b>	613-370	<b>E-F3</b>				
617366	<b>F3</b>	617-366	<b>F4</b>	617366	<b>PBM4</b>	617366	<b>F4</b>

620364	<b>F4</b>	620-363	<b>F2</b>	620363	<b>PBM2</b>	620363	<b>F2</b>
620364	<b>H-F4</b>	620-363	<b>E-F2</b>				
624359	<b>F5</b>			621359	<b>PBM11</b>		
625356	<b>F6</b>	625-356	<b>F7</b>			625356	<b>F7</b>
636354	<b>F7</b>	636-353	<b>F6</b>	636354	<b>PBM6</b>	636353	<b>F6</b>
626357	<b>F13</b>	626-375	<b>F1</b>	626357	<b>PBM1</b>	626357	<b>F1</b>
626357	<b>H-F13</b>	626-357	<b>E-F1</b>			626357	<b>S-TIM1</b>
640354	<b>H-F51</b>	640-354	<b>E-FD7</b>			640354	<b>S-TIM27</b>
570495	<b>BaF2</b>	570-494	<b>BAF2</b>	570493	<b>BAM2</b>	570494	<b>BAF2</b>
580539	<b>BaF3</b>	580-537	<b>BAFL4</b>	580537	<b>BAL4</b>	580539	<b>BALF4</b>
583465	<b>BaF4</b>	583-465	<b>BAF3</b>	583464	<b>BAM3</b>	583465	<b>BAF3</b>
606439	<b>BaF5</b>	606-439	<b>BAF4</b>	606437	<b>BAM4</b>	606437	<b>BAF4</b>
608462	<b>BaF6</b>	608-462	<b>BAF7</b>			609464	<b>BAF52</b>
614400	<b>BaF7</b>						
626391	<b>BaF8</b>	626-391	<b>BAFD1</b>	626392	<b>BAM21</b>	626390	<b>BASF1</b>
622531	<b>ZBaF1</b>	622-531	<b>BACED2</b>	622532	<b>BSM22</b>	622533	<b>SSK2</b>
622532	<b>H-ZBaF1</b>			622532	<b>S-BSM22</b>	622533	<b>B-SSK2</b>
640483	<b>ZBaF2</b>						
657511	<b>H-ZBaF3</b>						
664355	<b>ZBaF4</b>	664-359	<b>BAFD2</b>	664358	<b>BAH22</b>	664358	<b>BASF2</b>
671473	<b>H-ZBaF5</b>			670473	<b>S-BAH10</b>		
667484	<b>H-ZBaF16</b>	667-483	<b>BAF11</b>	667483	<b>S-BAH11</b>	667484	<b>BAFN11</b>
702412	<b>H-ZBaF20</b>	702-412	<b>BAFD7</b>	702412	<b>S-BAH27</b>	702410	<b>N-BASF52</b>
723380	<b>H-ZBaF21</b>	723-380	<b>BAFD8</b>	723380	<b>SBAH28</b>		
658509	<b>H-ZBaF50</b>	658-509	<b>BACED5</b>	658509	<b>S-BSM25</b>	658509	<b>N-SSK5</b>
670472	<b>H-ZBaF52</b>	670-472	<b>BAF10</b>	670473	<b>S-BAH10</b>	670471	<b>N-BAF10</b>
648338	<b>ZF1</b>	648-338	<b>FD2</b>	648338	<b>PBM22</b>	648339	<b>SF2</b>

648338	<b>H-ZF1</b>	648-338	<b>E-FD2</b>	648338	<b>S-TIM22</b>		
673322	<b>ZF2</b>	673-322	<b>FD5</b>	673321	<b>PBM25</b>	673322	<b>SF5</b>
673322	<b>H-ZF2</b>	673-322	<b>E-FD5</b>	673321	<b>S-TIM25</b>	673322	<b>N-SF5</b>
717295	<b>ZF3</b>	717-295	<b>FD1</b>	717295	<b>PBH1</b>	717296	<b>SF1</b>
717295	<b>H-ZF3</b>	717-295	<b>E-FD1</b>	717295	<b>S-TIH1</b>	717296	<b>N-SF1</b>
728283	<b>ZF4</b>	728-283	<b>FD10</b>	728285	<b>PBH10</b>	728284	<b>SF10</b>
728283	<b>H-ZF4</b>	728-283	<b>E-FD10</b>	728285	<b>S-TIH10</b>	728285	<b>N-SF10</b>
740282	<b>ZF5</b>	740-282	<b>FD3</b>	740283	<b>PBH3</b>	740282	<b>SF3</b>
740283	<b>H-ZF5</b>			740283	<b>S-TIH3</b>		
755275	<b>ZF6</b>	755-275	<b>FD4</b>	755275	<b>PBH4</b>	755274	<b>SF4</b>
755275	<b>H-ZF6</b>	755-275	<b>E-FD4</b>	755275	<b>S-TIH4</b>	755274	<b>N-SF4</b>
805255	<b>ZF7L</b>	805-255	<b>FD6</b>	805254	<b>PBH6</b>	805254	<b>SF6</b>
805255	<b>H-ZF7LA</b>	805-255	<b>FD60</b>	805254	<b>S-TIH6</b>	805254	<b>N-SF6</b>
654337	<b>ZF8</b>	654-337	<b>FD9</b>	654336	<b>PBM29</b>	654337	<b>SF9</b>
689312	<b>ZF10</b>	689-312	<b>FD8</b>	689311	<b>PBM28</b>	689313	<b>SF8</b>
689312	<b>H-ZF10</b>	689-312	<b>E-FD8</b>	689311	<b>S-TIM28</b>	689313	<b>N-SF8</b>
699301	<b>ZF11</b>	699-301	<b>FD15</b>	699301	<b>PBM35</b>	699302	<b>SF15</b>
699301	<b>H-ZF11</b>	699-301	<b>E-FD15</b>	699301	<b>S-TIM35</b>	699302	<b>N-SF15</b>
762266	<b>ZF12</b>	762-266	<b>FD14</b>	762265	<b>PBH14</b>	762265	<b>SF14</b>
762266	<b>H-ZF12</b>	762-266	<b>FD140</b>	762265	<b>S-TIH14</b>		
785258	<b>ZF13</b>	785-257	<b>FD11</b>	785257	<b>PBH11</b>	785257	<b>SF11</b>
785257	<b>H-ZF13</b>	785-257	<b>FD110</b>	785257	<b>S-TIH11</b>	785257	<b>N-SF11</b>
667330	<b>H-ZF39</b>			667330	<b>S-TIM39</b>		
741278	<b>ZF50</b>	741-278	<b>FD13</b>	741278	<b>PBH13</b>	741276	<b>SF13</b>
741278	<b>H-ZF50</b>	741-278	<b>E-FD13</b>	741278	<b>S-TIH13</b>		
785261	<b>ZF51</b>	785-261	<b>FDS3</b>	785262	<b>PBH23</b>	785261	<b>SF56</b>
847238	<b>ZF52</b>	847-238	<b>FDS9</b>	847239	<b>PBH53</b>	847236	<b>SF57</b>

847238	<b>H-ZF52A</b>	847-238	<b>FDS90</b>	847238	<b>S-TIH53</b>	847238	<b>N-SF57</b>
923209	<b>H-ZF62</b>	923-209	<b>E-FDS1</b>			923209	<b>N-SF66</b>
923189	<b>H-ZF72A</b>			923189	<b>S-NPH2</b>		
946180	<b>H-ZF88</b>	946-180	<b>FDS18</b>				
612441	<b>TF3</b>						
613441	<b>H-TF3L</b>	613-443	<b>ADF40</b>	613442	<b>BPM51</b>		
717479	<b>H-LaF2</b>	717-480	<b>LAF3</b>	717479	<b>S-LAM3</b>		
744449	<b>H-LaF3B</b>	744-449	<b>LAF2</b>	744448	<b>S-LAM2</b>	744449	<b>N-LAF2</b>
750350	<b>H-LaF4</b>	750-350	<b>E-LAF7</b>	750353	<b>S-LAM7</b>	749348	<b>N-LAF7</b>
754375	<b>H-LaFL5</b>						
757477	<b>H-LaF6LA</b>	757-477	<b>NBF2</b>	757478	<b>S-LAM54</b>		
782371	<b>H-LaF7</b>	783-361	<b>NBFD7</b>	783362	<b>S-LAM62</b>		
788475	<b>H-LaF10LA</b>	788-475	<b>TAF4</b>	788474	<b>S-LAH64</b>	788475	<b>N-LAF21</b>
773496	<b>H-LaF50B</b>	773-496	<b>TAF1</b>	773496	<b>S-LAH66</b>	773496	<b>N-LAF34</b>
700481	<b>H-LaF51</b>			700481	<b>S-LAM51</b>		
786442	<b>H-LaF52</b>	786-439	<b>NBFD11</b>	786442	<b>S-LAH51</b>	786441	<b>N-LAF33</b>
743492	<b>H-LaF53</b>	743-492	<b>NBF1</b>	743493	<b>S-LAM60</b>	743494	<b>N-LAF35</b>
800422	<b>H-LaF54</b>	800-423	<b>NBFD12</b>	800422	<b>S-LAH52</b>	800424	<b>N-LAF36</b>
720437	<b>H-LaF62</b>			720437	<b>S-LAM52</b>		
802443	<b>H-ZLaF1</b>	802-443	<b>NBFD14</b>			802443	<b>LASF11</b>
803468	<b>H-ZLaF2A</b>			803467	<b>LAH62</b>	803468	<b>LASF1</b>
855366	<b>H-ZLaF3</b>	855-366	<b>TAFD13</b>			855366	<b>LASF13</b>
804466	<b>H-ZLaF50B</b>	804-465	<b>TAF3</b>	804466	<b>S-LAH65</b>	804465	<b>N-LASF44</b>
805396	<b>H-ZLaF51</b>	805-396	<b>NBFD3</b>	804396	<b>S-LAH63</b>		
806410	<b>H-ZLaF52</b>	806-407	<b>NBFD13</b>	806409	<b>S-LAH53</b>	806406	<b>N-LASF43</b>
834372	<b>H-ZLaF53A</b>	834-373	<b>NBFD10</b>	834372	<b>S-LAH60</b>	834373	<b>N-LASF40</b>
835427	<b>H-ZLaF55C</b>	835-427	<b>TAFD5F</b>	835427	<b>S-LAH55</b>	835431	<b>N-LASF41</b>

806333	<b>H-ZLaF56B</b>	806-333	<b>NBFD15</b>				
801350	<b>H-ZLaF66</b>			801350	<b>S-LAM66</b>	801350	<b>N-LASF45</b>
883408	<b>H-ZLaF68B</b>	883-408	<b>TAFD30</b>	883408	<b>S-LAH58</b>	883410	<b>N-LASF31</b>
850323	<b>H-ZLaF71</b>			850323	<b>S-LAH71</b>	850322	<b>N-LASF9</b>
850301	<b>H-ZLaF76</b>						
901371	<b>H-ZLaF78</b>						
<b>CDGM</b>		<b>HOYA</b>		<b>OHARA</b>		<b>SCHOTT</b>	
<b>代码</b>	<b>牌号</b>	<b>代码</b>	<b>牌号</b>	<b>代码</b>	<b>牌号</b>	<b>代码</b>	<b>牌号</b>
583594	<b>D-ZK2</b>	583-595	<b>M-BACD12</b>	583594	<b>L-BAL42</b>		
589612	<b>D-ZK3</b>	589-613	<b>M-BACD5N</b>	589612	<b>L-BAL35</b>		
609579	<b>D-ZK79</b>						
518635	<b>D-K59</b>						
694531	<b>D-LaK6</b>	694-532	<b>M-LAC130</b>	694532	<b>L-LAL13</b>		
669554	<b>D-LaK70</b>						
731405	<b>D-LaF79</b>	731-405	<b>M-LAF81</b>	731405	<b>L-LAM69</b>		
810410	<b>D-ZLaF52LA</b>						
735488	<b>D-LaF82L</b>						
689311	<b>D-ZF10</b>	689-312	<b>M-FD80</b>	689311	<b>L-TIM28</b>		
768492	<b>D-LaF050</b>	768-492	<b>M-TAF101</b>				
743493	<b>D-LaF53</b>	743-493	<b>M-NBF1</b>				
854406	<b>D-ZLaF85L</b>						